

Appendix D
Photographs



Photo 1 - Small pocket of PSS wetland along Upper Fountain Creek (Figure 2-1 and Appendix B, Woodland Park 4a).



Photo 2 - Fringe PEM wetlands along Upper Fountain Creek between US 24 lanes (Figure 2-1 and Appendix B, Cascade 1a).



Photo 3 - Large PSS wetland south of Monument Lake (Figure 2-1 and Appendix B, Palmer Lake 3a).



Photo 4 - Pocket of PSS wetland and a large PEM wetland in a park along Dirty Woman Creek (Figure 2-1 and Appendix B, Monument 2a).



Photo 5 - Pockets of PEM and PSS wetlands along Monument Creek (Figure 2-1 and Appendix B, Pikeview 7a).



Photo 6 - PEM wetlands along eroded section of Fountain Creek channel (Figure 2-1 and Appendix B, Colorado Springs 9a).



Photo 7 - PEM wetland not in the original data (Figure 2-1 and Appendix B, Colorado Springs 9a).



Photo 8 - Narrow PEM/PSS wetland fringe along Fountain Creek at base of cut bank (Figure 2-1 and Appendix B, Fountain 7a).



Photo 9 - PEM wetland fringe along Fountain Creek (Figure 2-1 and Appendix B, Pinon 2a).



Photo 10 - PSS wetland fringe with pockets of PEM wetland along Fountain Creek (Figure 2-1 and Appendix B, Northeast Pueblo 2a).



Photo 11 - High potential preservation area along Fountain Creek (Figure 2-1 and Appendix B, Pinon 1a).



Photo 12 - High potential restoration area along Jimmy Camp Creek (Figure 2-1 and Appendix B, Fountain 4b).