

Table of Contents

Executive Summary ES - 1

1 Introduction

1.1 Plan Overview 1 - 3

1.2 Vision and Purposes

1.2.1 Vision..... 1 - 3

1.2.2 Purposes..... 1 - 3

1.3 Goals and Objectives 1 - 4

1.4 Watershed Issues..... 1 - 6

1.5 Watershed Processes 1 - 6

1.5.1 Erosion 1 - 6

1.5.2 Sedimentation..... 1 - 7

1.5.3 Flooding 1 - 7

1.6 Economic Impacts 1 - 7

1.7 Regulatory Programs..... 1 - 8

1.8 Watershed Activities..... 1 - 8

2 Background and Overview

2.1 Watershed History

2.1.1 Pre-Colonial Settlement 2 - 1

2.1.2 Colonial Settlement and Westward Expansion..... 2 - 1

2.1.3 Watershed Planning and Management History..... 2 - 3

2.1.4 Flooding History 2 - 4

2.1.5 Monument Creek Floodway Improvements..... 2 - 6

2.1.6 Municipal Water Supply Development

2.1.6.1 Colorado Springs’ Water Supply..... 2 - 6

2.1.6.2 City of Pueblo and Pueblo County 2 - 9

2.1.7 Agricultural Water Supply Development..... 2 - 9

2.1.8 Wastewater and Industrial Discharges..... 2 - 9

2.1.9 U.S. Army Corp of Engineers..... 2 - 11

2.2 Physical Characteristics

2.2.1 Geology 2 - 13

2.2.2 Soils 2 - 14

2.2.3 Fluvial Geomorphology in the Fountain Creek Watershed 2 - 15

2.3 Climate and Precipitation 2 - 15

2.4 Streamflow..... 2 - 16

2.5 Sediment Transport..... 2 - 16

2.6 Potential Flood Hazards..... 2 - 17

2.7 Land Use 2 - 17

2.8 Impervious Surface Area 2 - 18

2.9 Stream Gauge Monitoring Network 2 - 19

2.10 Population and Socioeconomic Characteristics 2 - 21

3 Methodology: The Watershed Approach

3.1 Organization and Structure of the Plan 3 - 1

3.1.1 Fountain Creek Headwaters..... 3 - 4

3.1.2 Monument Creek..... 3 - 4

3.1.3 Colorado Springs Composite..... 3 - 5

3.1.4 Lower Fountain Creek 3 - 6

3.2 Methodology 3 - 6

4 Characterization of Watershed Problems and Issues

4.1 Fountain Creek Headwaters Subwatershed 4 - 1

4.1.1 Channel and Watershed Characteristics 4 - 1

4.1.1.1 Hydrologic Characteristics 4 - 1

4.1.1.2 Physical Characteristics 4 - 4

4.1.2 Channel and Watershed Erosion and Sedimentation Characteristics

4.1.2.1 Woodland Park and Teller County 4 - 4

4.1.2.2 Green Mountain Falls and Teller County 4 - 6

4.1.2.3 Manitou Springs 4 - 6

4.1.2.4 Colorado Springs 4 - 9

4.1.3 Stream Channel Alignment 4 - 10

4.1.4 Infrastructure 4 - 11

4.1.5 Urban Development 4 - 11

4.1.6 Agriculture 4 - 11

4.1.7 Ranking and Prioritization of Watershed Problems and Issues 4 - 11

4.2 Monument Creek Subwatershed 4 - 13

4.2.1 Channel and Watershed Characteristics 4 - 13

4.2.1.1 Hydrologic Characteristics 4 - 13

4.2.1.2 Physical Characteristics 4 - 15

4.2.2 Channel and Watershed Erosion and Sedimentation Characteristics 4 - 15

4.2.3 Stream Channel Alignment 4 - 21

4.2.3.1 Critical Reach Analysis 4 - 23

4.2.4 Infrastructure 4 - 26

4.2.5 Urban Development..... 4 - 27

4.2.6 Agriculture 4 - 27

4.2.7 Ranking and Prioritization of Watershed Problems and Issues 4 - 27

4.3 Colorado Springs Composite Subwatershed..... 4 - 29

4.3.1 Channel and Watershed Characteristics..... 4 - 29

4.3.1.1 Hydrologic Characteristics..... 4 - 29

4.3.1.2 Physical Characteristics..... 4 - 31

4.3.2 Channel and Watershed Erosion and Sedimentation Characteristics 4 - 32

4.3.3 Stream Channel Alignment 4 - 38

4.3.3.1 Critical Reach Analysis..... 4 - 38

4.3.4 Infrastructure..... 4 - 40

4.3.5 Urban Development..... 4 - 40

4.3.6 Agriculture 4 - 40

4.3.7 Ranking and Prioritization of Watershed Problems and Issues 4 - 41

4.4 Lower Fountain Creek Subwatershed 4 - 43

4.4.1 Channel and Watershed Characteristics..... 4 - 44

4.4.1.1 Hydrologic Characteristics..... 4 - 44

4.4.1.2 Physical Characteristics..... 4 - 44

4.4.2 Channel and Watershed Erosion and Sedimentation Characteristics 4 - 44

4.4.2.1 City of Pueblo 4 - 45

4.4.2.2 North Pueblo County 4 - 51

4.4.3 Stream Channel Alignment 4 - 53

4.4.3.1 Critical Reach Analysis..... 4 - 53

4.4.4 Infrastructure..... 4 - 55

4.4.5 Urban Development..... 4 - 56

4.4.6 Agriculture 4 - 56

4.4.7 Ranking and Prioritization of Watershed Problems and
Issues 4 - 56

5 Characterization and Evaluation of Channel Instability

5.1 Defining Stream Instability 5 - 1

5.2 Stream Channel Classification..... 5 - 3

5.2.1 Fountain Creek Headwaters 5 - 5

5.2.2 Monument Creek 5 - 5

5.2.3 Colorado Springs Composite 5 - 5

5.2.4 Lower Fountain Creek 5 - 5

5.3 Causes of Channel Instability

5.3.1 Drainage Basin Hydrology..... 5 - 5

5.3.2 Sediment Transport..... 5 - 6

5.3.2.1 Floodplain Encroachment 5 - 8

5.3.2.2 Increased Floodplain Vegetation Density..... 5 - 8

5.3.2.3 Increased Bank Erosion 5 - 10

5.3.3 Channel Bank Protection and Grade Control 5 - 10

6 Summary and Evaluation of Policy and Technical and Management Strategies

6.1 Summary of Current State and Federal Regulatory Programs 6 - 1

6.1.1 Floodplain 6 - 1

6.1.1.1 FEMA National Flood Insurance Program
(NFIP) 6 - 2

- 6.1.2 Riparian and Wetland Habitat**
 - 6.1.2.1 Clean Water Act, Section 404 Regulations 6 - 2**
 - 6.1.2.2 Colorado Natural Heritage Program 6 - 3**
 - 6.1.2.3 Colorado Division of Wildlife
(State Guidance and Enforcement) 6 - 3**
 - 6.1.2.4 U.S. Fish and Wildlife Service..... 6 - 3**
 - 6.1.2.5 Endangered Species Act
(61 FR 27978, June 3, 1996)..... 6 - 4**
- 6.1.3 Stormwater and Urban Runoff**
 - 6.1.3.1 National Pollutant Discharge Elimination System
Phase I and II..... 6 - 4**
- 6.1.4 Construction Discharge Permits 6 - 6**
- 6.1.5 Water Resource Development 6 - 6**
- 6.1.6 Water Quality**
 - 6.1.6.1 Clean Water Act, Section 303(d) Regulations 6 - 7**
- 6.1.7 Wastewater Treatment Plant and Industrial Discharge
Permits..... 6 - 8**
- 6.2 Summary of Current Local Regulatory Programs..... 6 - 9**
 - 6.2.1 Regulatory Program Review and Summary 6 - 10**
 - 6.2.2 Review and Comparison of Policies and Ordinances..... 6 - 11**
 - 6.2.2.1 Policies and Regulations Common to All Communities in the
Watershed 6 - 11**
 - 6.2.2.2 Communities With Ordinances or Policies Unique to the
Watershed 6 - 14**
 - 6.2.3 Policy Strategies**
 - 6.2.3.1 Watershed Concerns Not Addressed in Existing Documents . 6 - 17**
 - 6.2.3.2 Implementation of New Policies..... 6 - 20**

6.3 Other Watershed Policies 6 - 20

6.4 Technical Strategies 6 - 22

6.4.1 Channel Stabilization Methods..... 6 - 23

6.4.1.1 Grade Control..... 6 - 23

6.4.1.2 Bank Stabilization 6 - 24

7 Conclusions and Recommendations and Implementation Strategies

7.1 Conclusions 7 - 1

7.2 Future Planning Activities 7 - 2

7.3 Recommendations and Implementation Strategies..... 7 - 3

8 Plan Approval..... 8 - 1

9 References 9 - 1

10 Bibliography..... 10 - 1

11 Glossary 11 - 1

Appendices

- Appendix A – Summary of Fountain Creek Watershed Stream Gauge Data**
- Appendix B – GIS Database Development**
- Appendix C – Airphoto Rectification and Feature Extraction Methodologies**
- Appendix D – Compilation of Drainage Basin Planning Study Data**
- Appendix E – Summary of Channel Stability Characteristics.**
- Appendix F – Fountain Creek Watershed Policy Matrix**
- Appendix G – Fountain Creek Watershed Activity Matrix**
- Appendix H – Army Corps of Engineers Watershed Study Scope of Work**
- Appendix I - Urbanization Flow Chart**

Appendix J – Summary of Public Comments and Responses**Tables**

Table 2 – 1:	Summary of five largest streamflow events on Fountain Creek at Pueblo, Colorado, and magnitude and general location of precipitation (USGS, 2000)	2 – 6
Table 2 – 2:	Municipal Water Systems in the Fountain Creek Watershed	2 – 9
Table 2 – 3:	Permitted Wastewater Treatment Plant Discharges in the Fountain Creek Watershed	2 – 10
Table 2 – 4:	Completed U.S. Army Corps of Engineers Reports (K. Schafer, personal communication, April 2001)	2 – 12
Table 2 – 5:	Soil Characteristics Summary	2 – 14
Table 2 – 6:	Impervious Surface Area	2 - 18
Table 2 – 7:	Fountain Creek Watershed Stream Monitoring Network	2 - 19
Table 2 – 8:	Summary of Fountain Creek Watershed Population Estimates	2 – 21
Table 3 – 1:	Tabulation of the HUC Framework for the Fountain Creek Watershed	3 – 2
Table 4 – 1:	Fountain Creek Headwaters Subwatershed Stream Segments	4 - 12
Table 4 – 2:	Monument Creek Headwaters Stream Segments	4 - 28
Table 4 – 3:	Avg. Cut and Fill values for various survey stations at different cross-sections from 1998-2000.	4 – 30
Table 4 – 4	Colorado Springs Composite Stream Segments	4 - 42
Table 4 – 5	Fountain Creek Headwaters Stream Segments	4 - 58
Table 5 – 1:	Summary of Delineative Criteria for Broad-level (Level 1 and 2) Classification (Rosgen, 1994)	5 – 4
Table 5 – 2:	Factors Affecting Sediment Transport	5 – 7
Table 6 – 1:	Relevant Watershed Organizations	6 – 21

Figures

Figure 1 – 1:	Fountain Creek Watershed Regional Reference Map	1 – 2
Figure 2 – 1	Fountain Creek Watershed Stream Monitoring Network	2 – 20
Figure 3 – 1:	Map of the HUC Framework for the Fountain Creek Watershed	3 – 3
Figure 4 – 1:	Fountain Creek Watershed Hydrologic Features	4 – 2
Figure 4 – 2:	Fountain Creek Headwaters Subwatershed	4 – 3
Figure 4 – 3:	Upper Fountain Creek Channel Profile	4 – 5
Figure 4 – 4:	Monument Creek Subwatershed	4 – 14
Figure 4 – 5:	The Monument Creek Channel Profile	4 – 16
Figure 4 – 6:	The Cottonwood Creek Channel Profile	4 – 17
Figure 4 – 7:	Colorado Springs Composite Subwatershed	4 – 30
Figure 4 – 8:	Lower Fountain Creek Channel Profile – Section I	4 – 32
Figure 4 – 9:	Jimmy Camp Creek Channel Profile	4 – 33
Figure 4 – 10.	Cross-section at the Fountain Creek at Nevada site for April 1999, April 2000, and April 2001.	4 – 34
Figure 4 – 11:	City of Colorado Springs Cross-Section Survey Sites.	4 – 36
Figure 4 – 12:	Lower Fountain Creek Subwatershed	4 – 43

Figure 4 – 13:	Lower Fountain Creek Channel Profile – Section II	4 – 46
Figure 4 – 14:	Williams Creek Channel Profile	4 – 46
Figure 4 – 15:	The Frost-Hanna Critical Reach	4 – 54
Figure 5 – 1:	Lane’s relationship for qualitative analysis of channel stability (Lane, 1955)	5 – 2

Photos

Photo 4 – 1:	Sediment in Upper Fountain Creek	4 – 5
Photo 4 – 2:	Realignment of Upper Fountain Creek	4 – 7
Photo 4 – 3:	Bank erosion Downstream of Woodland Park.	4 – 7
Photo 4 – 4:	Channel Sediment Below Bridge in Upper Fountain Creek	4 – 8
Photo 4 – 5:	Flooding of Manitou Springs streets during the storms and floods of 1999.	4 – 8
Photo 4 – 6:	Fountain Creek Channel Improvements Near 21 st Street.	4 – 9
Photo 4 – 7:	Erosion in Fountain Creek Upstream of the Monument Creek Confluence.	4 – 10
Photo 4 – 8:	Beaver Dams on Upper Monument Creek	4 – 17
Photo 4 – 9:	Fill placement in the Floodplain of Upper Monument Creek	4 – 18
Photo 4 – 10:	Concrete Channel Lining at the Woodmen Road Bridge	4 – 19
Photo 4 – 11:	Old Concrete Check structures in the Lower Monument Creek Channel.	4 – 20
Photo 4 – 12:	Bank Erosion Damage on Cottonwood Creek	4 – 20
Photo 4 – 13:	Channel Bed Degradation on Cottonwood Creek	4 – 21
Photo 4 – 14:	New Boulder Drop Structure on Cottonwood Creek	4 – 22
Photo 4 – 15:	New Boulder Drop Structure on Lower Monument Creek	4 – 22
Photo 4 – 16:	Channel Degradation downstream of Red Ranch Drive and Monument Creek	4 – 23
Photo 4 – 17:	Channel Degradation in Black Forest Creek	4 - 24
Photo 4 – 18:	Old Drop Structures on Cottonwood Creek	4 - 25
Photo 4 – 19:	Templeton Gap Floodway	4 - 31
Photo 4 – 20:	Erosion of Fountain Creek at KAO campground from 1999 Flood	4 – 37
Photo 4 – 21:	Meander Migration and Erosion Upstream of the Old Pueblo Highway Bridge on Fountain Creek	4 – 37
Photo 4 – 22:	Streambank Erosion on Fountain Creek in the City of Fountain.	4 – 38
Photo 4 – 23:	Pedestrian Bridge Crossing Jimmy Camp Creek	4 - 39
Photo 4 – 24:	Confluence of Fountain Creek with the Arkansas River	4 – 48
Photo 4 – 25:	Sediment Accumulating in the Arkansas River	4 – 48
Photo 4 – 26:	Sediment in a Park near the Mouth of Fountain Creek	4 – 49
Photo 4 – 27:	City of Pueblo: Storms Drains Emptying into Fountain Creek	4 – 50
Photo 4 – 28:	Bank Erosion in Fountain Creek at Target Store	4 – 50
Photo 4 – 29:	Pinon Bridge Crossing Fountain Creek	4 – 51
Photo 4 – 30:	Bank Erosion along Overton Road	4 – 52
Photo 4 – 27:	Bank Erosion along Lower Fountain Creek at Subdivision	4 – 52